

#### Product Line Affected

DiPosDeka\_17

#### Cutter Bodies Affected

DM2Q, DM5Q, DM6Q



# DIPOS<sup>®</sup> DEKA<sup>™</sup>

## Phase Out Notice

**EFFECTIVE FEBRUARY 1st, 2026**


This notice is to inform you that DiPosDeka\_17 cutter series DM2Q, DM5Q & DM6Q are phased out. Inserts will be phased out in time.

Once the remaining cutter stock is sold, users can either request replacement cutters by submitting a Quote Request (for price & delivery) through their local Ingersoll Sales Representative OR use the following chart to identify a stocked alternative that uses a different insert.

The following contacts can be used to inquire further:

[TechnicalSupport@ingersoll-imc.com](mailto:TechnicalSupport@ingersoll-imc.com)

1-800-380-0852

| Discontinued  | Alternatives  |  |   |
|---|---|--|---|
| DiPosDeka_17  | CougarMill  | CougarMill HSHR  | ISO Plus  |
|  |  |  |  |
|   |  |  |  |
| DM2Q-06R01  | 5C2M-06R01  | 5C4M-06R01   | DL5T-60R01  |
| DM2Q-08R01  | 5C2M-08R01  | 5C4M-08R01   |   |
| DM2Q-10R01  | 5C2M-10R01  | 5C4M-10R01   |   |
| DM2Q-12R01  | 5C2M-12R01  | 5C4M-12R01   |   |
| DM6Q-03R01  |   |  | DL5T-30R01  |
| DM5Q-04R01  | 5C2M-04R01  | 5C4M-04R01   | DL5T-40R01  |
| DM6Q-04R01  | 5C2M-04R01  | 5C4M-04R01   | DL5T-40R01  |
| DM6Q-05R01  |   |  | DL5T-50R01  |
| DM5Q-06R01  | 5C2M-06R02  | 5C4M-06R01   | DL5T-60R01  |
| DM6Q-06R01  | 5C2M-06R01  | 5C4M-06R01   | DL5T-60R01  |
| DM5Q-08R01  | 5C2M-08R02  | 5C4M-08R01   |   |
| DM6Q-08R01  | 5C2M-08R01  | 5C4M-08R01   |   |
| DM6Q-10R01  | 5C2M-10R01  | 5C4M-10R01   |   |
| DM6Q-12R01  | 5C2M-12R01  | 5C4M-12R01   |   |